

## **Spray Rusty Penetrator**

## **Technical Data Sheet**

Page 1 of 1

**Properties:** Spray Rusty Penetrator is a fast working rust penetrant based on

mixtures of mineral oils, graphite particles, corrosion inhibitors and

solvents. The product is acid-free and free of silicone.

**Application Area:** Spray Rusty Penetrator has been specially formulated of a combination of

penetrating and lubricants. The product is an ideal assistant for dissolving tightly seized corroded screws, bolts and nuts. Typical applications such

as

- loosens exhaust nuts and manifold nuts

- loosens tie roads

loosens stud bolts

- loosens pulleys and shafts

 lubricates and provide corrosion protection of springs, chain links, gear wheels, suspension components, locks and moving parts of machinery e.g. gardening tools, stone processing machines, etc. As containing graphite particles it is also extremely useful when used for lubricating where machinery can be left for long periods of time in weathering

conditions.

**Instructions for Use:** 1. Shake well before use.

2. Remove excess corrosion by using a wire brush.

3. Apply Spray Rusty Penetrator liberally and allow to penetrate for a

while.

4. Loosen parts screw off or get moving

Technical Data: Colour: black

Density: 0.728 g/cm³ Heat resistance: max. 500°C VOC: 643 g/l

**Storage:** 30 months, cool and dry.

**Health & Safety:** Read Material Safety Data Sheet before handling or using this product.

Sales References: Packaging: 400 ml aerosol

Customs Tariff Code: 3405 3000 Part Number: 88559

**Important Notice:** The above information is based on the latest stage of development and

application technology. Due to a multiplicity of different influencing

factors, this information – as well as other oral or written technical advises – must be considered as non-binding hints. The user is obliged in each particular case to conduct performance tests, including but not limited to trails of the product, in an inconspicuous area or fabrication of a sample

piece